



advanced coating systems

CLEAR TWO COMPONENT YELLOW RESISTANT EPOXY SEAL

GENERAL PRODUCT DESCRIPTION

XtraKote Sealer is a two component, high performance cycloaliphatic epoxy concrete floor sealer. Xtrakote Sealer provides a durable, high gloss finish which beautifies concrete for years. Its epoxy chemistry provides excellent bonding characteristics and its low viscosity allows deep penetrating into a concrete substrate. It is generally applied as a 12 to 16 mil coating system. Its design features provide for the highest industrial demands. Advantages:

- Essentially odorless
- Self-priming VOC Compliant
- High gloss
- Withstands medium to heavy traffic
- Chemical resistant
- Able to be applied over damp concrete
- No amine blush
- Can be applied over ten day old concrete

PRODUCT DATA

Volumetric Ratio:	2 to 1
Solids:	100% (+ or - 1%)
Coverage:	100 S/F per gal. at 16 mils
	135 S/F per gal. at 12 mils
Application Temperature:	65-90°F and 5° above the dew point
Thinning:	Not required
Pot Life:	15-20 minutes
Working time on floor:	20-30 minutes
Cure Time:	10 hours (walking)
	24 hours (traffic)
Critical recoat time:	24 hours
Shelf life:	12 months
USDA Food and Beverage:	Meets requirements

PHYSICAL PROPERTIES

PROPERTY	VALUE	REFERENCE
Compressive Strength	8,880 psi	ASTM C 579
Flexural Strength	8,100 psi	ASTM D 790
Tensile Strength	5,700 psi	ASTM D 638
Bond to Concrete	350 psi concrete fails at this point	ASTM D 4541
Coefficient of Friction	0.6 minimum	ASTM D 2047
Taber Abrasion	37 mgs	ASTM D 4060 CS 17 Wheels
Flammability	Self-extinguishing	ASTM D 635
Hardness, Shore D	84	ASTM D 2240
Flash Point	>200°F	ASTM D 93

INDUSTRIAL APPLICATIONS

The uniqueness and universality of its chemistry allows Xtra Kote Sealer to be used in the following applications:

- Manufacturing .
- Aerospace
- Food Preparation
- Power Plants
- **Electronic Plants**
- Warehouses
- Aisle ways
- Clean rooms
- Automotive
- Schools
- Aisles
- Docks

XTRAKOTE SEALER

CONCRETE PREPARATION

Before the coating is applied, the concrete must be: Clean – Contaminants removed

Profiled – Surface etched Sound – Cracks repaired

Mechanical methods are preferred for preparing concrete prior to coating application. Shot-blasting, diamond grinding, scarifying, and scabbling are all acceptable methods. The concrete profile should approximate 60-80 grit sandpaper after preparation.

PATCHING

Voids, cracks, and imperfections will be seen in finished coating if the concrete is not patched correctly. Patch concrete with Petra Patch. After the patching material has cured, diamond grind patch the concrete. If a non-Petra patching material is used, make sure that it is a two-part epoxy patch. Always test unproven products by applying patch material first, then Petra coating system next. Check to see if bonding is firm.

MIXING

The ratio of XtraKote Sealer is 2 to 1. That is, two parts of A (resin), to one part of B (hardener). Generally, three mixed gallons is ideal for application. Mix the following with a drill and jiffler mixer.

- 1. Part A does not require pre-mixing. If using the 15 gallon kit, pour out 2 gallons into an empty 5 gallon bucket which then becomes the mixing bucket. (The three gallon kit allows the Part A bucket to be used as the complete mixing bucket, since the Part A comes in a three and a half gallon bucket.)
- 2. Add one gallon of part B and mix for 60-90 seconds.
- 3. Immediately apply to the floor. XtraKote Sealer in mass has a short pot life of approximately 15-20 minutes. Once poured out on the floor, 20-30 minutes of working time can generally be expected.

APPLICATION PROCESS

XtraKote Sealer for a nominal 12 to 16 mil coating system is applied in two coats. For estimation, use 135 S/F (12 mils) to 100 S/F (16 mils) as a coverage rate. The following is for a 16 mil system:

- 1. Always apply in descending temperatures. Concrete is porous and traps air. In ascending temperatures (generally mornings), the air expands and can cause out gassing in the coating. It is safer to apply coatings in the late afternoon, especially for exterior applications. Optimum ambient temperature should be between 65-90°F during application.
- 2. Mix three gallons of resin using above mixing instructions.
- Apply approximately 200 S/F per gallon by immediately pouring out on surface in a ribbon, while walking and pouring at the same time until bucket is empty.
- 4. Using a window squeegee on a pole, pull XtraKote Sealer over substrate. As a first coat over bare concrete, pull resin as thin as possible while still wetting out concrete and uniformly covering
- 5. Using a 3/8" non-shedding phenolic (plastic) core paint roller, roll the coating forwards and backwards.
- 6. Lastly, backroll in the opposite direction from step 5.
- 7. Apply second coat by repeating steps 1-6 the next day.

PRODUCT LIMITATION

Ground level concrete slabs emit moisture vapor. The allowable moisture emissions for concrete is 3 lbs. 1000 S/F over a twentyfour hour period. If moisture is above this level, then blistering and delamination of coating may occur. A calcium chloride test should be performed to determine concrete moisture level. If moisture levels exceed the 3 lb. limit, a concrete moisture vapor control system should be used first before applying coating system. Please contact Petra technical department for approved systems.

Coating systems are susceptible to cracking if the concrete moves or separates below the coating. Hence, joint and crack treatment should be reviewed prior to coating application. As a general rule, control joints (saw cuts) and random cracks should be saw cut or chased first then filled with Petra Patch or similar approved hard epoxy product. Construction joints (two slabs which meet and hence move) should be treated. After the coating has been applied and cured, saw cut through the coating over construction joints.

COLORS

XtraKote Sealer is available in clear only. Note: Generally, clear sealers look good on new concrete or concrete in good condition only. The discoloration, stains, and patches on older concrete show through clear sealers. When concrete is discolored, stained, and patched, it is best to apply XtraKote TC which is available in a variety of standard colors.

PACKAGING

XtraKote Sealer is available in two different kit sizes:

		Part A	Part B
3	Gallon Kit	2 gal.	1 gal.
15	Gallon Kit	10 gal.	5 gal.

CLEANUP

XtraKote Sealer, while in an unreacted state, may be cleaned up with water and degreaser. Isopropyl alcohol or acetone may be needed once the resin begins hardening. Lastly, a stronger solvent may be required if the resin is nearly set up.

WARRANTY

Petra Polymers products are warranted for one year after date of application. Please refer to the Petra Polymer's Limited Material Warranty for additional clarification.

SAFETY

Consult XtraKote Sealer material safety data sheet. Avoid Xtra-Kote Sealer contact with skin. Some individuals may be allergic to epoxy.



Information expressed in this data sheet is correct to the best of our knowledge. The technical data sheet does not constitute a warranty, expressed or implied as to the performance of this product. The use and application of this product is beyond our control. Warranty and liability therefore is limited to the replacement only for defective materials. Technical information is subjected to change without cause.